

Manual Saddle Peeler

For PE pipes



Scope of application:

The Manual Saddle Peeler is solely meant for removing the oxide layer on polyethylene pipes as preparation for electro-fusion (EF) welding of saddle fittings..

Dimension range:

Metric: 110mm and above

Inch: 4 Inch and above

Preparation:

Use a clean, grease-free cloth to remove dirt, sand and grime from the surface to be peeled.

Check the pipe surface for indented foreign bodies and dirt before peeling.

Führen Sie eine Sichtprüfung auf Schäden am Werkzeug durch und achten Sie dabei besonders auf das Schälmesser.



FHS Poly | fhs.com.au | 1300 347 111

Contact us for supply




FHS Poly | fhs.com.au | 1300 347 111
Contact us for supply

Peeling:

Grip the tool by the two handles and place it on the marked area. The peeling blade should be positioned at approx. 2/3 of the blade width on the area to be peeled.

Application:



Disposal:

The product must be disposed of in an environmentally friendly manner sorted by materials..

Material specifications:

Handles	Rollers Fixing material Peeling blade	Body Carrier feed wagon
		



Plasson LTD. Maagan Michael, D.N. Menashe, 3780500, Israel
Tel: +972-4-6394711 | Fax: +972-4-6394766
www.plasson.com | info@plasson.com